



COTSWORKS ERRATA SHEET

Errata Number: 10001

Document Type: Datasheets

Original Date(s): 23JUN2017 (RCPs)
03JUL2019 (LC-801)

Related Devices: RCP-5G-SX
RCP-10G-SX
LC-801

This Errata describes the deviation from current user documentation. The material classification for ARINC801 spring clips used in COTSWORKS' devices was previously incorrectly identified.

Previous identification: Beryllium Copper

Amended identification: UNS30100 Stainless Steel

The following documents have been amended to address this inconsistency:

- 944-00001-27 RCP-10G-SX Datasheet (updated 09JUL2020)
- 944-00002-18 RCP-10G-SX Datasheet Long version (updated 09JUL2020)
- 944-00027-17 RCP-5G-SX Datasheet Long version (updated 09JUL2020)
- 944-00028-14 RCP-5G-SX Datasheet (updated 09JUL2020)
- 944-00056-11 LC-801 Datasheet (updated 09JUL2020)

Please Contact COTSWORKS for any questions at info@cotsworks.com

Authorization	
<input checked="" type="checkbox"/> Approved for public release	
Platform Product Manager: [REDACTED]	Date: 8JUL2020
Director of QMS: [REDACTED]	Date: 9JUL2020

