



COTSWORKS ERRATA SHEET

Errata Number: 10002

Document Type: Datasheets
Original Date(s): 28-APR-21

Related Devices: RJ-155M-FX

This Errata describes the deviation from the current user documentation listed above. The RX Output Voltage specification was previously incorrectly identified.

Previous identification: RX *Differential* Output Voltage

Amended identification: RX *Single-Ended* Output Voltage

The following documents have been amended to address this inconsistency:

944-00017-15 RJ-155M-FX Datasheet

Please Contact COTSWORKS for any questions at info@cotsworks.com

| | |
|---|---------------------------|
| Authorization | |
| <input checked="" type="checkbox"/> Approved for public release | |
| Platform Product Manager: [REDACTED] | Date: 09-Nov-22 |
| Director of QMS: [REDACTED] | Date: Nov. 9, 2022 |

